


















PRODUCT SELECTOR GUIDE

PRODUCT	FUNCTION	DURABILITY LOWER 1 - 6 HIGHER	CLEANS?	RECOMMENDED SURFACES	SPREAD / COVERAGE	EASE OF USE EASY 1 - 6 HARD
No.920 	Cleans, restores, and preps for wax	Has no protective properties	YES-fine-mild abrasive removes wax, staining, discoloration, and mild-moderate oxidation	Fiberglass, gel coat, single stage, lacquered, enameled paint and light colored clear coats (white and silver tones only)	16 fl oz for every 250-500 sq. ft. of surface area; coverage depends on level of contamination and need for reapplication	1* 
No.925 	Shines, Preserves Protects	4* 	NO- Has no restorative properties	Fiberglass, gel coats, clear coats, painted and non painted metals, painted plastic	16 fl oz for every 1,200-2,000 sq. ft of clean surface area	3* 
No.885 	Shines, Preserves Protects	6* 	NO- Has no restorative properties	Fiberglass, gel coats, clear coats, painted and non painted metals, painted plastic	12 fl oz for every 1,400-2,200 sq. ft. of clean surface area	6* 
No.870 	Cleans, beautifies and protects	2* 	YES-fine-mild abrasive removes staining, discoloration & early oxidation	Fiberglass, gel coat, single stage, lacquered, enameled paint and light colored clear coats (white and silver tones only)	16 fl oz for every 500-1,000 sq. ft of surface area (early contamination or oxidation)	2* 
No.850 	Cleans, restores, and protects	2* 	YES-medium cut abrasive removes salt deposits, minor rust and tarnish	Non-painted metals with mild contamination or oxidation (e.g. aluminum, stainless steel, chrome, brass, copper)	16 fl oz for every 200-400 sq. ft of surface area; coverage depends on level of contamination and need for reapplication	2* 
No.855 	Gently cleans, conditions, and protects	3* 	YES-very fine cleanser removes light staining /oxidation	Sealed leather & vinyl. NOT for canvas, unsealed leather, fabric/upholstery	16 fl oz for every 300-500 sq. ft of clean surface area	3* 

*Durability and Ease-of-Use scales are intended for general comparative purposes within the Collinite brand of products only. Please note that maintenance, as well as exposure to several factors (snow, salt, rain, UV etc.) will determine the durability/protective life of a wax. **Spread/Coverage varies on surface condition, prep work, and detailing methods/proficiency.